

## RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 11708

RECEIVED FROM

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080053-5

CHARGE TO QUANTITY RECEIVED	ACA Division of LIMA Corp.							DATE REC'D. 2-27-77	P.O. NO. 6436	VENDOR PACKING SLIP NO. 1098
	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER			
322	NOTED									
	DRAWING NO. AND DESCRIPTION							QUANTITY		REMARKS
6	79122-12	Relay time Agstat AF-2255 (30-120 sec., set for 75 sec.) LFTW S. S. (322-00000-79-0-13-1)		6						
6	730125-20	Relay Time Delay, Agstat AF-22 ES (20-40 sec., set for 20 sec.) (322-00000-167-0-13-1)		10						

*W.E. Fonda*  
W.E. Fonda  
1/28/77

RECEIVED  
BY *J. Barcelas*INSPECTED  
BY *M.W.*DATE *2-28-77*REJECTS RETURNED  
ON SHIP. MEMO NO.

RECEIVED FROM

RECEIVING INSPECTION REPORT  
HYCON MFG. COMPANY  
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11742

CHARGE TO QUANTITY RECEIVED	PLANT #							DATE REC'D. 4-2-77	P.O. NO.	VENDOR PACKING SLIP NO.
	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER			
322		142	0	16						
	DRAWING NO. AND DESCRIPTION							QUANTITY		REMARKS
6	732-76	Gear Asmly, Cam Idler		24						

*W.E. Fonda*  
W.E. Fonda  
1/28/77

RECEIVED  
BY *J. Barcelas*

INSPECTED

DATE *1/28/77*

ON SHIP. MEMO NO.

HMC 103

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080053-5